



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
5 01-00	100 HR INSP 6,807	Work Card Task Card	Airframe	11-Sep-2009 H: 5628.80	H: 100			H: 5728.80	H: 99.50
5 01-00	24 MONTH INSPECTION 14,958	Work Card Task Card	Airframe	11-Sep-2009 H: 5628.80	H: 100			H: 5728.80	H: 99.50
5 01-00	CORROSION INSPECTION 14,957	Work Card Task Card	Airframe	11-Sep-2009 H: 5628.80	H: 100			H: 5728.80	H: 99.50
5 01-02	300 HR INSP 6,815	Work Card Task Card	Airframe	11-Sep-2008 H: 5564.20	H: 300			H: 5864.20	H: 234.90
5 01-03	FUEL CELL CLN 6,942	Work Card Task Card	Airframe	05-Jan-2009 H: 5584.60	M: 12			05-Jan-2010	D: -27
5 01-03A	12 MO FUEL SYS INSP 6,808 P/N: 206-364-604-101 S/N: 1916	Work Card Task Card	Airframe	05-Jan-2009 H: 5584.60 L: 34228	M: 12			05-Jan-2010	D: -27
5 01-04	FAA ANNUAL INSP 6,938	Work Card Task Card	N/A On Condition	30-Oct-2007 H: 5422.40					
5 01-06	1200 HR INSP 6,809	Work Card Task Card	Airframe	15-Jul-2003 H: 4675.00	H: 1200			H: 5875.00	H: 245.70
5 01-07	1200 HR TAILBOOM INSP 6,810	Work Card Task Card	Airframe	24-Oct-2007 H: 5422.50	H: 1200			H: 6622.50	H: 993.20





Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
5 10-001	CARGO HOOK OVERHAUL 6,891 P/N: 528-022-01 S/N: 1163	Work Card Task Card	Airframe	19-Jun-2007 H: 5376.50	M: 60 H: 1000		M: 0 H: 0.00	19-Jun-2012 H: 6376.50	M: 28 D: 18 H: 747.20
5 10-002	NDT HOOK WEIGHING SYS INSP 6,970 P/N: N/A S/N: N/A	Work Card Task Card	Airframe	16-Mar-2009 H: 5598.70	M: 24		M: 0	31-Mar-2011	M: 13 D: 30
8 00-001	AIRCRAFT WEIGHING INSP 6,840	Work Card	Airframe	05-Jan-2009 H: 5584.60	M: 36			05-Jan-2012	M: 23 D: 4
12 20-002	200 HR LUBE & SERVICE 6,812	Work Card	Airframe	08-Sep-2009 H: 5628.80	H: 200			H: 5828.80	H: 199.50
12 20-003	TAIL ROTOR DRIVESHAFT BEARINGS, LUBE 6,986	Work Card	Airframe	10-Apr-2009 H: 5598.70	M: 12 H: 300			30-Apr-2010 H: 5898.70	M: 2 D: 29 H: 269.40
12 20-004	TAIL ROTOR DRIVE SPLINE ADAPTORS, LUBE 6,985	Work Card	Airframe	09-Sep-2008 H: 5564.20	H: 300			H: 5864.20	H: 234.90
12 20-005	HYDRAULIC FILTER CLEANING 14,930	Work Card	Airframe	09-Sep-2008 H: 5564.20	H: 300			H: 5864.20	H: 234.90
12 20-006	HYDRAULIC FILTER REPLACEMENT 14,929 P/N: 206-076-034-006	Work Card	Airframe	H: 4967.40	H: 1200			H: 6167.40	H: 538.10
23 00-001	LICENSE, FCC MOBILE FCC FORM INSP 6,963	Work Card	On Condition	19-Aug-2006					



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
24 00-001	BATTERY TEMP SENSOR CALIBRATION	Work Card		18-Jun-2007 H: 5371.50	H: 600			H: 5971.50	H: 342.20
	6,883		Airframe						
24 01-01	BATTERY DEEP CYCLE/CAPACITANCE CHECK	Work Card		14-Aug-2009 H: 5627.80	M: 12 H: 200		M: 0 H: 0.00	14-Aug-2010 H: 5827.80	M: 6 D: 13 H: 198.50
	6,882 P/N: M31700 S/N: 10001512		Airframe						
24 30-001	START GERNERATOR OVERHAUL	Work Card		15-Jun-2004 H: 4915.70	H: 1000		H: 0.00	H: 5915.70	H: 286.40
	6,980 P/N: 23081-018 S/N: 5112		Airframe						
26 20-007	PORTABLE FIRE BOTTLE HYDROSTATIC CK	Work Card		04-Dec-2003 H: 4795.70	M: 120			04-Dec-2013	M: 46 D: 3
	6,974		Airframe						
27 10-001	M/R FLT CNTRL SYS BOLTS, INP	Work Card		22-Apr-2009 H: 5598.70	M: 24			30-Apr-2011	M: 14 D: 29
	6,965		Airframe						
27 10-010	CYCLIC TUBE-L/H REPLACEMENT	Work Card		19-Nov-2003 H: 4791.10	H: 4800		H: 0.00	H: 9591.10	H: 3961.80
	6,925 P/N: 206-001-193-001 S/N: A-7206		Airframe						
27 10-011	CYCLIC TUBE- R/H REPLACEMENT	Work Card		19-Nov-2003 H: 4791.10	H: 4800		H: 0.00	H: 9591.10	H: 3961.80
	6,924 P/N: 206-001-193-001 S/N: A-7178		Airframe						
27 20-002	CYCLIC HYD SERVO ACTUATOR-LH OVERHAUL	Work Card		27-Aug-1998 H: 2434.00	H: 3600		H: 0.00	H: 6034.00	H: 404.70
	6,922 P/N: 206-076-062-101 S/N: RH-4779A		Airframe						
27 20-003	CYCLIC HYD SERVO ACTUATOR-RH OVERHAUL	Work Card		27-Aug-1998 H: 2434.00	H: 3600		H: 0.00	H: 6034.00	H: 404.70
	6,923 P/N: 206-076-062-101 S/N: RH-4778A		Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
27 20-004	COLLECTIVE HYD SERVO ACTUATOR, OVERHAUL 6,916 P/N: 206-076-062-101 S/N: RH-4569A	Work Card	Airframe	17-Oct-2000 H: 3589.00	H: 3600		H: 0.00	H: 7189.00	H: 1559.70
28 20-001	PUMP, FUEL BOOST 6,975	Work Card	On Condition						
28 20-002	PUMP, FUEL BOOST AFT 6,976	Work Card	On Condition						
34 00-00	CHANGE, ARNAV GPS RECEIVER 14,927 P/N: 453-1060-00 S/N: 077002	Work Card	On Condition	18-Mar-2008 H: 5473.40			H: 0		
34 00-01	TRANSPONDER CERTIFICATION 7,019	Work Card	Airframe	23-Jan-2008 H: 5473.40 L: 6162	M: 24			23-Jan-2010	D: -9
34 00-02	ELT INSP 6,929 P/N: 453-6604 S/N: 07617	Work Card	Airframe	18-May-2009 H: 5599.30	M: 12		M: 0	31-May-2010	M: 3 D: 30
34 00-02A	ELT BATTERY REPLACE 6,928 P/N: 452-6504	Work Card	Airframe	19-May-2008 H: 5474.10	M: 60		M: 0	30-Apr-2013	M: 38 D: 29
34 00-03	ALTITUDE BLIND ENCODER TEST 6,841	Work Card	Airframe	23-Jan-2008 H: 5473.40	M: 24			23-Jan-2010	D: -9
34 00-04	PILOT/STATIC SYS TEST 6,971	Work Card	Airframe	23-Jan-2008 H: 5473.40 L: 5739	M: 24			23-Jan-2010	D: -9



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
34 01-03	COMPASS CALIBRATION	Work Card		18-May-2009 H: 5599.00	M: 12			18-May-2010	M: 3 D: 17
	6,917		Airframe						
34 01-04	ALTIMETER CALIBRATION	Work Card		30-Jan-2008 H: 5473.40 L: 6162	M: 24			30-Jan-2010	D: -2
	6,930		Airframe						
62	ASB TAIL ROTOR BLADE 206-016-201-131 CHECK AND REMOVAL FROM SERVICE - ONE TIME	Work Card		11-Oct-2004 H: 5009.10					
	14,889		On Condition						
	Notes / Compliance	NOT APPLICABLE DUE TO S/Ns CS 8150 AND 8147							
62 10-0010	HUB ASSEMBLY, MAIN ROTOR OVERHAUL	Work Card	OVERHAUL	11-Mar-2009 H: 5589.40	H: 2400		H: 0.00	H: 7989.40	H: 2360.10
	6,953 P/N: 206-011-100-105 S/N: HB-432		Airframe						
62 10-0011	HUB ASSEMBLY, SPECIAL TEARDOWN INSP	Work Card		11-Mar-2009 H: 5589.40	H: 1200		H: 0.00	H: 6789.40	H: 1160.10
	6,954 P/N: 206-011-100-105 S/N: HB-432		Airframe						
62 10-011	YOKE, MAIN ROTOR OVERHAUL	Work Card	OVERHAUL	11-Mar-2009 H: 5589.40			H: 0		
	7,024 P/N: 206-011-149-105 S/N: HB-1640		On Condition						
62 10-012A	GRIP, MAIN ROTOR REPLACEMENT	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 4800		H: 2372.80	H: 8016.60	H: 2387.30
	6,951 P/N: 206-011-132-113A S/N: A-7295		Airframe						
62 10-012B	GRIP, MAIN ROTOR REPLACEMENT	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 4800		H: 2372.80	H: 8016.60	H: 2387.30
	6,950 P/N: 206-011-132-113A S/N: A-7293		Airframe						
62 10-013	TRUNNION, MAIN ROTOR REPL (24,000R)	Work Card		11-Mar-2009 H: 5589.40	R: 14334		H: 0	R: 14334	R: 4820
	7,020 P/N: 206-011-113-103 S/N: HB-2029		Airframe						





Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
62 10-014A	PIN, MAIN ROTOR STRAP REPLACEMENT 6,972 P/N: 206-011-125-001 S/N: OP-4340	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 1200		H: 0.00	H: 6789.40	H: 1160.10
62 10-014B	PIN, MAIN ROTOR STRAP REPLACEMENT 6,973 P/N: 206-011-125-001 S/N: OP-4381	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 1200		H: 0.00	H: 6789.40	H: 1160.10
62 10-015A	LATCH BOLT-MAIN ROTOR, REPLACEMENT 6,960 P/N: 206-011-260-101 S/N: DI-21448	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 1200		H: 0.00	H: 6789.40	H: 1160.10
62 10-015B	LATCH BOLT-MAIN ROTOR, REPLACEMENT 6,961 P/N: 206-011-260-101 S/N: DI-21342	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 1200		H: 0.00	H: 6789.40	H: 1160.10
62 10-016A	FITTING, MAIN ROTOR STRAP REPLACEMENT 6,940 P/N: 206-011-150-105 S/N: HB-7403	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 2400		H: 0.00	H: 7989.40	H: 2360.10
62 10-016B	FITTING, MAIN ROTOR STRAP REPLACEMENT 6,939 P/N: 206-011-150-105 S/N: HB-7408	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	H: 2400		H: 0.00	H: 7989.40	H: 2360.10
62 10-017A	STRAP, MAIN ROTOR REPLACEMENT 6,981 P/N: 206-011-154-107 S/N: LP47072	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	M: 24 H: 1200		M: 0 H: 0.00	11-Mar-2011 H: 6789.40	M: 13 D: 10 H: 1160.10
62 10-017B	STRAP, MAIN ROTOR REPLACEMENT 6,982 P/N: 206-011-154-107 S/N: LP47165	Work Card	LIFE LIMIT	11-Mar-2009 H: 5589.40	M: 24 H: 1200		M: 0 H: 0.00	11-Mar-2011 H: 6789.40	M: 13 D: 10 H: 1160.10
62 10-018A	BLADE, MAIN ROTOR REPLACEMENT 6,886 P/N: 206-015-001-115 S/N: A-3788	Work Card		31-Oct-2000 H: 3589.00	H: 3600		H: 0.00	H: 7189.00	H: 1559.70



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
62 10-018B	BLADE, MAIN ROTOR REPLACEMENT 6,885 P/N: 206-015-001-115 S/N: A-3776	Work Card	Airframe	31-Oct-2000 H: 3589.00	H: 3600		H: 0.00	H: 7189.00	H: 1559.70
63 20-001	ROTOR BRAKE SYS OVERHAUL 6,977	Work Card	Airframe	10-Jul-1999 H: 2895.00	H: 3000			H: 5895.00	H: 265.70
63 30-002A	KAFLEX DRIVESHAFT REPLACEMENT 6,959 P/N: 206-340-300-107 S/N: KC1495	Work Card	Airframe	15-Jun-2004 H: 4915.70	H: 5000		H: 0.00	H: 9915.70	H: 4286.40
63 30-003A	FREEWHEELING ASSEMBLY OVERHAUL 6,941 P/N: 406-040-500-113 S/N: A-1886	Work Card	Airframe	10-Jul-1999 H: 2895.00	H: 3000		H: 0.00	H: 5895.00	H: 265.70
64 30-0010	HUB ASSEMBLY, TAIL ROTOR OVERHAUL 6,955 P/N: 206-011-810-151 S/N: A-4704	Work Card	Airframe	04-Feb-2004 H: 4819.60	H: 2500		H: 0.00	H: 7319.60	H: 1690.30
64 30-002A	YOKE, TAIL ROTOR REPLACEMENT 7,026 P/N: 206-011-819-109 S/N: HBFS 2315	Work Card	Airframe	03-Feb-2004 H: 4819.60	H: 5000		H: 0.00	H: 9819.60	H: 4190.30
64 30-002B	YOKE, TAIL ROTOR OVERHAUL 7,025 P/N: 206-011-819-105 S/N: HBFS-2315	Work Card	Airframe	04-Feb-2004 H: 4819.60	H: 2500		H: 0.00	H: 7319.60	H: 1690.30
64 30-003	BLADE, TAIL ROTOR REPLACEMENT 6,887 P/N: 206-016-201-131 S/N: CS8147V	Work Card	Airframe	03-Feb-2004 H: 4819.60	H: 2500		H: 0.00	H: 7319.60	H: 1690.30
64 30-004	BLADE, TAIL ROTOR REPLACEMENT 6,888 P/N: 206-016-201-131 S/N: CS4849	Work Card	Airframe	15-Mar-2005 H: 5014.20	H: 2500		H: 231.10	H: 7283.10	H: 1653.80
64 30-005	TRUNNION, TAIL ROTOR OVERHAUL 7,021 P/N: 206-011-812-005	Work Card	Airframe	04-Feb-2004 H: 4819.60	H: 2500			H: 7319.60	H: 1690.30



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
65 60-0001	GRBX ASSEMBLY,SPECIAL TEARDOWN INSP 6,948 P/N: 206-040-402-107 S/N: A-3710	Work Card	Airframe	08-Jul-1999 H: 2895.00	H: 3000			H: 5895.00	H: 265.70
65 60-0002	GRBX ASSEMBLY, TAIL ROTOR OVERHAUL 6,947 P/N: 206-040-402-107 S/N: A-3710	Work Card	Airframe		H: 6000		H: 0.00	H: 6000.00	H: 370.70
65 60-0003	BEARING DUPLEX, REPLACEMENT 6,884 P/N: 206-040-410-101 S/N: MB-683	Work Card	Airframe	08-Jul-1999 H: 2895.00	H: 3000		H: 0.00	H: 5895.00	H: 265.70
65 60-0005	DRIVESHAFT TAILROTOR, INSP 6,926	Work Card	Airframe	15-Jul-2003 H: 4675.00	H: 2400			H: 7075.00	H: 1445.70
66 00-001A	TRANSMISSION, OVERHAUL 7,018 P/N: 206-040-004-115 S/N: A-199	Work Card	Airframe	16-Jan-2003 H: 4488.00	H: 4500		H: 0.00	H: 8988.00	H: 3358.70
66 00-001B	TRANSMISSION, INSP 7,017 P/N: 206-040-004-115 S/N: A-199	Work Card	Airframe	16-Jan-2003 H: 4488.00	H: 1500			H: 5988.00	H: 358.70
66 20-001	MAIN ROTOR MAST, REPLACEMENT 6,966 P/N: 206-040-535-109 S/N: N113	Work Card	Airframe	10-Jul-1999 H: 2895.00 R: 1	H: 5000 R: 44000		H: 0.00	H: 7895.00 R: 44001	H: 2265.70 R: 34487
66 20-001A	MAST ASSEMBLY, MAIN ROTOR OVERHAUL 6,969 P/N: 206-040-014-107 S/N: 52054	Work Card	Airframe	10-Jul-1999 H: 2895.00	H: 3000		H: 0.00	H: 5895.00	H: 265.70
66 20-001B	MAST ASSEMBLY, BEARING INSP 6,967	Work Card	Airframe	16-Jan-2003 H: 4488.00	H: 1500			H: 5988.00	H: 358.70



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
66 20-001C	MAST ASSEMBLY, INTERNAL INSP 6,968	Work Card	Airframe	08-Sep-2009 H: 5628.80	M: 12			08-Sep-2010	M: 7 D: 7
67 10-001	LEVER, COLLECTIVE 6,962 P/N: 206-010-447-109FM S/N: RE-38	Work Card	Airframe	18-Nov-2003 H: 4791.10	H: 3632		H: 0.00	H: 8423.10	H: 2793.80
67 20-001	CNTRL TUBE, TAIL ROTOR INSP 6,915 P/N: 206-001-058-101	Work Card	Airframe	22-Apr-2009 H: 5598.70	M: 24 H: 1200			30-Apr-2011 H: 6798.70	M: 14 D: 29 H: 1169.40
67 20-3010	SWASHPLATE ASSEMBLY, OVERHAUL 6,984 P/N: 206-010-450-101 S/N: RE-161	Work Card	Airframe	18-Nov-2003 H: 4791.10	H: 4800		H: 0.00	H: 9591.10	H: 3961.80
67 20-3020	LINK, COLLECTIVE IDLER REPLACEMENT 6,964 P/N: 206-010-446-107FM S/N: RE-34	Work Card	Airframe	18-Nov-2003 H: 4791.10	H: 3632		H: 0.00	H: 8423.10	H: 2793.80
67 20-3030	SLEEVE, SWASHPLATE REPLACEMENT 6,979 P/N: 206-010-454-109 S/N: RE8224	Work Card	Airframe	18-Nov-2003 H: 4791.10	H: 4800		H: 0.00	H: 9591.10	H: 3961.80
67 20-3040	SUPPORT, SWASHPLATE REPLACEMENT 6,983 P/N: 206-010-445-113 S/N: RE-1108	Work Card	Airframe	18-Nov-2003 H: 4791.10	H: 4800		H: 0.00	H: 9591.10	H: 3961.80
67 20-3050	DUPLEX BEARING, SWASHPLATE REPLACEMENT 6,927 P/N: 206-010-443-001 S/N: 18170	Work Card	Airframe	18-Sep-1995 H: 980.00	H: 4800		H: 0.00	H: 5780.00	H: 150.70
72 00-001	ENG OVERHAUL 6,937 P/N: 250-C30P S/N: CAE-895742	Work Card	On Condition	29-Nov-1997 H: 2042.00			H: 0		



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
72 00-002	ENG 150 HR INSP 6,931	Work Card	Airframe	03-Jun-2009 H: 5603.60	H: 150			H: 5753.60	H: 124.30
72 00-003	ENG 300 HR INSP 6,933	Work Card	Airframe	06-Feb-2008 H: 5473.40 C: 6162.00	H: 300			H: 5773.40	H: 144.10
72 00-004	ENG 600 HR INSP 6,934	Work Card	Airframe	06-Feb-2008 H: 5473.40 C: 6162.00	H: 600			H: 6073.40	H: 444.10
72 00-005	ENG 2000 HR INSP 6,932	Work Card	Airframe	15-Nov-2001 H: 3977.00	H: 2000			H: 5977.00	H: 347.70
72 10-001	GRBX C30, OVERHAUL 6,949 P/N: 23035178 S/N: 95750	Work Card	Engine 1	06-Dec-2001 H: 3977.20	H: 4000		H: 0.00	H: 7977.20	H: 2412.90
72 30-001	COMPRESSOR OVERHAUL 6,918	Work Card	On Condition	22-Nov-2001 H: 3977.20					
72 30-002	IMPELLER REPLACEMENT (12500H/25000C) 6,958 P/N: 23030976 S/N: LP94120	Work Card	Engine 1	16-Aug-1993 C: 1.00	H: 12500 C: 25000.00		H: 0.00 C: 0.00	H: 12500.00 C: 25001.00	H: 6935.70 C: 18472.00
72 50-000	TURBINE C30P REPLACEMENT 7,022 P/N: 23035128 S/N: 98092	Work Card	Engine 1	15-Nov-2001 H: 3977.20 C: 4758.00	H: 2000 C: 3000.00		H: 0.00 C: 0.00	H: 5977.20 C: 7758.00	H: 412.90 C: 1229.00
72 50-001	1ST STAGE TURBINE WHEEL REPLACEMENT 6,811 P/N: 23053299 S/N: X511976	Work Card	Engine 1	21-Nov-2001 H: 3977.20 C: 4758.00	H: 2025 C: 3000.00		H: 0.00 C: 0.00	H: 6002.20 C: 7758.00	H: 437.90 C: 1229.00



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
72 50-002	2ND STAGE TURBINE WHEEL REPLACEMENT 6,813 P/N: 23032280 S/N: X503538	Work Card	Engine 1	21-Nov-2001 H: 3977.20 C: 4758.00	H: 2025 C: 3000.00		H: 0.00 C: 0.00	H: 6002.20 C: 7758.00	H: 437.90 C: 1229.00
72 50-003	3RD STAGE TURBINE WHEEL REPLACEMENT 6,816 P/N: 6898663 S/N: HX93953	Work Card	Engine 1	21-Nov-2001 H: 3977.20 C: 4758.00	H: 4550 C: 6000.00		H: 0.00 C: 0.00	H: 8527.20 C: 10758.00	H: 2962.90 C: 4229.00
72 50-004	4TH STAGE TURBINE WHEEL REPLACEMENT 6,817 P/N: 23066744 S/N: X503998	Work Card	Engine 1	21-Nov-2001 H: 3977.20 C: 4758.00	H: 4550 C: 6000.00		H: 0.00 C: 0.00	H: 8527.20 C: 10758.00	H: 2962.90 C: 4229.00
73 10-001	FUEL PUMP, TRW OVERHAUL 6,945 P/N: 6896822 S/N: T-0677	Work Card	Engine 1	12-Oct-1999 H: 2989.50	H: 3000		H: 0.00	H: 5989.50	H: 425.20
73 10-002	FUEL NOZ O/H (SEE CEB-A-73-3118) 6,944 P/N: 23077067 S/N: IWP09777	Work Card	Engine 1	15-Jun-2004 H: 4850.70	H: 2000		H: 0.00	H: 6850.70	H: 1286.40
73 20-001	FUEL CNTRL BENDIX, OVERHAUL 6,943 P/N: 23070613 S/N: 328826	Work Card	Engine 1	09-Jun-2004 H: 4850.70	H: 2500		H: 0.00	H: 7350.70	H: 1786.40
73 20-002	GOVERNOR, BENDIX OVERHAUL 6,946 P/N: 23070101 S/N: 24710	Work Card	Engine 1	16-Jun-2005 H: 5089.80	H: 2000		H: 0.00	H: 7089.80	H: 1525.50
75 30-001	BLEED VLV, OVERHAUL 6,889 P/N: 23005366 S/N: FF59296	Work Card	Airframe	13-Jan-2003 H: 4428.00	H: 1500		H: 0.00	H: 5928.00	H: 298.70
76 00-00	CHANGE, LINEAR ACTUATOR 14,928 P/N: 206-062-721-109 S/N: 831	Work Card	On Condition	18-Mar-2008 H: 5473.40			H: 0		



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
79 00-01	ENGINE OIL CHANGE	Work Card		11-Mar-2009 H: 5589.40	M: 12 H: 600		M: 0 H: 0.00	31-Mar-2010 H: 6189.40	M: 1 D: 30 H: 560.10
6,935			Airframe						
79 20-000	EXTERNAL FACET OIL FILTER	Work Card		11-Mar-2009 H: 5589.40	M: 12 H: 300		M: 0 H: 0.00	11-Mar-2010 H: 5889.40	M: 1 D: 10 H: 260.10
6,936	P/N: 038088-08		Airframe						
79 20-001	SCAVENGE OIL FLTR IMPENDING BYPASS CK	Work Card		06-Feb-2008 H: 5473.40 L: 6162	H: 600			H: 6073.40	H: 444.10
6,978			Airframe						
CSL-A-3062 PART 1	CSL-A-3062 PART 1	Work Card		23-Nov-2001 H: 3977.20 C: 4758.00	H: 2000			H: 5977.20	H: 412.90
6,919			Engine 1						
CSL-A-3062 PART 2	CSL-A-3062 PART 2	Work Card		23-Nov-2001 H: 4042.00	H: 2000			H: 6042.00	H: 412.70
6,920			Airframe						
CSL-A-3136	C/W CSL-A-3136	Work Card		07-Jun-1995 H: 805.00					
6,921			Airframe						
CEB 72-3202	C/W CEB 72-3202	Work Card		07-Jun-1995 H: 805.00					
6,892			Airframe						
CEB 73-3118	ENGINE FUEL DELIVERY - RELEASE OF NEW FUEL NOZZLE (250-C30P - S/N CAE895742)	Work Card		15-Jun-2004 H: 4850.70					
14,888	P/N: 23077067 S/N: IWP09777		Engine 1						
CEB A-72-3252	ENGINE, TURBINE - INSPECTION OF 1ST-STAGE NOZZLE SHIELD DOME	Work Card		15-Jun-2007 H: 5371.50					
14,886	P/N: 6892828		Engine 1						
	Notes / Compliance	RECURRING INSPECTION NO LONGER REQUIRED WITH REPLACEMENT OF 1ST STAGE NOZZLE SHIELD P/N 23073566							



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
CEB-72-3247	C/W CEB-72-3247	Work Card		24-Jan-2001 H: 3695.00					
6,893			Airframe						
CEB-73-3070	C/W CEB-73-3070	Work Card		23-Jan-1998 H: 2137.00					
6,894			Airframe						
CEB-73-3071	C/W CEB-73-3071	Work Card		12-Jul-1994 H: 245.00					
6,895			Airframe						
CEB-73-3112	N/A CEB-73-3112	Work Card		03-Apr-2003 H: 4573.60					
6,896			Airframe						
CEB-73-3114	CEB-73-3114	Work Card							
6,897			Airframe						
CEB-73-3118	CEB-73-3118	Work Card		15-Jun-2004 H: 4915.70					
14,875			Airframe						
CEB-A-72-3180	CEB-A-72-3180	Work Card							
6,898			Airframe						
CEB-A-72-3205 R3	CEB-A-72-3205 R3	Work Card							
6,899			Airframe						
CEB-A-72-3208 R2	C/W CEB-A-72-3208 R2	Work Card		30-Aug-1999 H: 2978.00					
6,901			Airframe						
CEB-A-72-3208	C/W CEB-A-72-3208	Work Card		12-Nov-1997 H: 2042.00					
6,900			Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
CEB-A-72-3217 R4 6,902	C/W CEB-A-72-3217 R4	Work Card	Airframe	22-Nov-2001 H: 4042.00					
CEB-A-72-3217 REV 3 6,903	C/W CEB-A-72-3217 REV 3	Work Card	Airframe	02-Jan-2001 H: 3636.00					
CEB-A-72-3229 6,904	C/W CEB-A-72-3229	Work Card	Airframe	29-Jun-1998 H: 2338.00					
CEB-A-72-3247 REV 2 6,905	C/W CEB-A-72-3247 REV 2	Work Card	Airframe	24-Jan-2001 H: 3695.00					
CEB-A-72-3252 6,906	C/W CEB-A-72-3252	Work Card	Airframe	02-Jan-2001 H: 3636.00					
CEB-A-72-3266 14,883	4TH STAGE WHEEL P/N: 23066744 S/N: X503998	Work Card	Airframe	16-Jun-2004 H: 4819.60					
CEB-A-72-3274 14,895	ENGINE, GEARBOX ASSY - INSPECTION AND REWORK S/N: HL39780	Work Card	N/A BY SN	17-Jul-2005 H: 5439.70					
CEB-A-72-3278 14,910	ALERT CEB TO INSPECT POWER TURBINE OUTER SHAFT	Work Card	COMPLIED WITH	30-Oct-2006 H: 5267.90					
	Notes / Compliance	NO FURTHER ACTION IS NECESSARY. P/N AND S/N DO NOT MATCH AFFECTED SHAFT LIST. NOTE: POWER TURBINE LAST MAJOR MAINTENANCE WAS 10/2001. SHAFTS AFFECTED ARE INSTALLED AFTER 10/2004.							
CEB-A-73-3068 R3 6,907	C/W CEB-A-73-3068 R3	Work Card	Airframe	19-Oct-1999 H: 3055.00					



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
CEB-A-73-3075 R1 6,909	FCU SCREW	Work Card	Airframe	01-Jun-2009 H: 5603.50	H: 150			H: 5753.50	H: 124.20
CEB-A-73-3075 6,908	C/W CEB-A-73-3075	Work Card	Airframe	27-Nov-1995 H: 1098.00					
CEB-A-73-3091 6,910	N/A CEB-A-73-3091	Work Card	Airframe	15-Sep-1997 H: 1963.00					
CEB-A-73-3102 R2 6,914	C/W CEB-A-73-3102 R2	Work Card	Airframe	23-Nov-2001 H: 4042.00					
CEB-A-73-3102 6,911	C/W CEB-A-73-3102	Work Card	Airframe	23-Nov-2001 H: 4042.00					
CEB-A-73-3102 6,913	C/W CEB-A-73-3102	Work Card	Airframe	07-May-1999 H: 2807.00					
CEB-A-73-3102 6,912	C/W CEB-A-73-3102	Work Card	Airframe	25-Oct-1998 H: 2532.00					
TB206L-001-206 6,987	TB206L-001-206	Work Card	Airframe						
TB206L-00-200 6,988	TB206L-00-200	Work Card	Airframe						
TB206L-02-207 6,989	TB206L-02-207	Work Card	Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
TB206L-94-168	TB206L-94-168	▶ Work Card							
6,990			Airframe						
TB206L-94-169	TB206L-94-169	▶ Work Card							
6,991			Airframe						
TB206L-94-170	TB206L-94-170	▶ Work Card							
6,992			Airframe						
TB206L-94-171	TB206L-94-171	▶ Work Card							
6,993			Airframe						
TB206L-94-172 PART 1	C/W TB206L-94-172 PART 1	▶ Work Card						18-Sep-1995 H: 980.00	
6,995			Airframe						
TB206L-94-172	TB206L-94-172	▶ Work Card							
6,994			Airframe						
TB206L-95-175	TB206L-95-175	▶ Work Card							
6,996			Airframe						
TB206L-95-178	TB206L-95-178	▶ Work Card							
6,997			Airframe						
TB206L-95-179	TB206L-95-179	▶ Work Card							
6,998			Airframe						
TB206L-95-180	TB206L-95-180	▶ Work Card							
6,999			Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
TB206L-95-182	TB206L-95-182	Work Card							
7,000			Airframe						
TB206L-95-183 RA	TB206L-95-183 RA	Work Card							
7,001			Airframe						
TB206L-96-186	TB206L-96-186	Work Card							
7,002			Airframe						
TB206L-96-187	TB206L-96-187	Work Card							
7,003			Airframe						
TB206L-96-188	TB206L-96-188	Work Card							
7,004			Airframe						
TB206L-96-189	TB206L-96-189	Work Card							
7,005			Airframe						
TB206L-96-190	C/W TB206L-96-190	Work Card		01-Jul-1999 H: 2895.00					
7,006			Airframe						
TB206L-96-191	TB206L-96-191	Work Card							
7,007			Airframe						
TB206L-97-193	TB206L-97-193	Work Card							
7,008			Airframe						
TB206L-97-194	TB206L-97-194	Work Card							
7,009			Airframe						





Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
TB206L-99-195	C/W TB206L-99-195	Work Card		07-Jul-2000 H: 2895.00					
7,011			Airframe						
TB206L-99-196	C/W TB206L-99-196	Work Card		03-Feb-2000 H: 3184.00					
7,012			Airframe						
TB206L-99-197	TB206L-99-197	Work Card							
7,013			Airframe						
TB206L-99-198	TB206L-99-198	Work Card							
7,014			Airframe						
TB206L-99-199 REV.1	TB206L-99-199 REV.1	Work Card							
7,016			Airframe						
TB206L-99-199	C/W SWASHPLATE DRIVE ASSY IMPROVED BUSHINGS	Work Card		03-Nov-2003 H: 4791.20					
14,885	P/N: 206-010-335-105		Airframe						
TB206L-99-199	C/W TB206L-99-199	Work Card		29-Apr-2000 H: 3308.00					
7,015			Airframe						
98 15-9004	C/W ONBOARD SYS #159-004	Work Card		24-Nov-1998 H: 2602.00					
6,890			Airframe						
206-09-121 REV C	LEVER ASSEMBLY P/N 206-001-401-111, 206-001-400-115, 206-001-400-111 AND 206-001-339-015 (ONE TIME INSPECTION)	Work Card	OPEN						
14,952			Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
98-04-131 ASB 206L-04-131 14,898	C/W ASB 206L-04-131 TAIL ROTOR BLADE CHECK	Work Card		21-Oct-2004 H: 5011.30					
	Notes / Compliance	NA -SERIAL # NOT IN ASB 206L-04-131							
ASB 206-09-124 14,948	HYDRAULIC SYSTEM OR CONTROL BOOST SWITCH - OFF CHECK	Work Card	N/A						
	Notes / Compliance	NA NOT REQUIRED ON 206L-4 MODEL AIRCRAFT							
ASB 206-09-125 14,949	ENGINE FUEL AND CONTROL - HONEYWELL MAIN FUEL CONTROLS - VERIFICATION OF FUEL FLOW CALIBRATION	Work Card	N/A						
	Notes / Compliance	NA NOT REQUIRED ON AIRCRAFT							
ASB 206L-01-123 REV A 14,903	DRIVESHAFT INSPECTION P/N 206-340-300-105	Work Card	COMPLIED WITH	04-Apr-2006 H: 5197.70					
	Notes / Compliance	PART I - INSPECTED RECORDS AND FOIUND DRIVE SHAFT TO BE 206-340-300-107 S/N KC1495. PART II - DOES NOT APPLY TO THIS PART NUMBER.							
ASB 206L-03-126 14,884	C/W ROLLS-ROYCE 250-30, INSPECTION 4TH STAGE TURBINE WHEEL P/N: 23066744 S/N: X503998	Work Card		04-Feb-2004 H: 4819.60					
ASB 206L-04-127 PART 3 14,892	REMOVE BALDE AND SENT TO ROTOR BLADE INC. P/N: 206-016-201-131 S/N: CS-8147V & CS 4849	Work Card	Alert	05-Nov-2004 H: 5014.20					
	Notes / Compliance	BLADES REPLACED BY S/N CS4849							



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
ASB 206L-04-129 PART 1	INSPECTION OF AFT BEARING CAP ON FREEWHEEL UNIT. S/NS A-1833 THRU A-1912 14,891 P/N: 406-040-509-101 S/N: A-757	Work Card	Alert	19-Sep-2004 H: 4998.90					
	Notes / Compliance								
	NOT APPLICABLE DUE TO S/N A-757								
ASB 206L-04-132	LOW FUEL LEVEL DETECTOR SWITCH P/N 206-063-613-003 - ONE TIME 14,887	Work Card		21-Oct-2004 H: 5011.30					
	Notes / Compliance								
	THE MOUNTING FLANGE IS RED , THE SWITCH IS NOT AFFECTED BY THIS SB AS PER ASB 206-063-613-003								
ASB 206L-05-133	TORQUE INDICATOR P/N 206-075-739-123 14,896 P/N: 206-075-739-113	Work Card	N/A	30-Jun-2005 H: 5090.20					
ASB 206L-05-135	ROLLS-ROYCE 250-C30P ENGINE GEARBOX ASSEMBLY - INSPECTION AND REWORK 14,893 S/N: HL39780	Work Card	N/A BY SN	07-Jul-2005 H: 5090.20					
ASB 206L-05-136	HYDRAULIC SERVO CLEVIS ASSEMBLY INSPECTION 14,899	Work Card		01-Nov-2005					
	Notes / Compliance								
	INSPECTED 2ND FOUND PN 206-076-062-101 SERVOS NOT AFFECTED BY THIS ASB. NOTE: SERVO P/N 206-076-062-103 ARE SERVOS REQUIRING INSPECTION								
ASB 206L-05-136	REVISION A HYDRAULIC SERVO ASSEMBLY INSPECTION 14,900	Work Card	N/A	30-Jan-2006 H: 5197.70					
	Notes / Compliance								
	INSPECTED AND FOUND THIS ASB DOES NOT APPLY TO THE SERVOS P/N 206-076-062-101 INSTALLED IN THIS AIRCRAFT								



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
ASB 206L-05-137 PART 2 14,901	ASB 206L-05-137 PART 2	Work Card	COMPLIED WITH	01-Feb-2006 H: 5197.70 L: 5 C: 5739.00 R: 33264					
	Notes / Compliance: SB CW NO FURTHER ACTION REQUIRED		Airframe						
ASB 206L-06-138 14,902	FLOAT INFLATION SQUIB IDENTIFICATION	Work Card	N/A	04-Apr-2006 H: 5197.70					
	Notes / Compliance: THIS ASB DOES NOT APPLY TO THIS AIRCRAFT. FLOATS NOT INSTALLED		Airframe						
ASB 206L-06-140 14,907	UPPER LEFT HAND TAILBOOM ATTACHMENT HARDWARE INSPECTION	Work Card	COMPLIED WITH	25-Oct-2006 H: 5267.40					
	Notes / Compliance: C/W ASB 206L-06-140 PART 1 UPPER LEFT-HAND FITTING IS NOT CRES STEEL. UPPER LEFT-HAND FITTING IS ALLOY (ALUMINUM) PART 2 IS NOT REQUIRED.		Airframe						
ASB 206L-06-141 14,909	INSPECTION OF HORIZONTAL STABILIZER	Work Card	N/A	26-Oct-2006 H: 5267.40					
	Notes / Compliance: INSPECTED HORIZONTAL STABILIZER AS PER PART 1 OF THIS ASB. FOUND HORIZONTAL INSTALLED ON THIS AIRCRAFT P/N 206-023-119-151 S/N BP 578 IS NOT AFFECTED BY THIS ASB.		Airframe						
ASB 206L-06-142 14,911	ASSURE COMPLIANCE OF ROLLSROYCE CEB A72-3278 POWER TURBINE OUTER SHAFT INSPECTION	Work Card	COMPLIED WITH	15-Nov-2006 H: 5272.90					
	Notes / Compliance: COMPLIED WITH ROLLS ROYCE CEB A-72-3278 AT ACTT 5267.9 ON 10/30/2006 AND FOUND P/N AND S/N DO NOT MATCH WITH AFFECTED LIST. NOTE: SHAFTS WERE INSTALLED PRIOR TO 10/2004.		Airframe						
ASB 206L-07-143 14,914	AERONAUTICAL ACCESSORIES PC SAFETY VALVE INSPECTION	Work Card	RECURRING	08-Sep-2009 H: 5628.80	H: 100			H: 5728.80	H: 99.50
			Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
ASB 206L-07-144	CARGO HOOK STRESS CORROSION CRACKS	Work Card	N/A	22-May-2007 H: 5353.30					
14,913			Airframe						
	Notes / Compliance	N/A THIS ASB APPLIES TO ONBOARD SYSTEM CARGO HOOKS. HOOK INSTALLED ON THIS AIRCRAFT							
ASB 206L-07-145	DISC ASSEMBLY P/N 3272-1 INSPECTION	Work Card	COMPLIED WITH	18-Jun-2007 H: 5371.50					
14,915			Airframe						
ASB 206L-07-146 REV A	POWER TURBINE STEADY STATE AVOIDANCE RANGE - REV A	Work Card	N/A	26-Feb-2008 H: 5473.40					
14,926			Airframe						
	Notes / Compliance	N/A BY AIRCRAFT SERIAL NUMBER							
ASB 206L-07-146	POWER TURBINE STEADY STATE AVOIDANCE RANGE	Work Card	N/A	17-Sep-2007 H: 5413.90					
14,918			Airframe						
	Notes / Compliance	N/A DUE TO MODEL TYPE							
ASB 206L-07-147	INSTALLATION OF FREEWHEEL AFT SEAL P/N 209-340-265-103	Work Card	COMPLIED WITH	30-Aug-2008 H: 5555.90					
14,920			Airframe						
	Notes / Compliance	COMPLIED WITH = INSTALLED P/N 209-340-265-103 ACCORDING TO ASB 208L-07-147							
ASB 206L-07-148 REV A	INSPECTION OF TAIL ROTOR BLADE ASSY	Work Card	COMPLIED WITH	12-Sep-2007 H: 5413.40					
14,916	P/N: 206-016-201-131 S/N: CS8147V/CS4849		Airframe						
ASB 206L-08-149	INSPECTION OF SUPPORT ASSEMBLY P/N 206-033-501-003 & 004	Work Card	COMPLIED WITH	07-Feb-2008 H: 5473.40					
14,925			Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
ASB 206L-08-150 14,934	N2 TURBINE AVOIDANCE RANGE FOR A/C WITH TRIDAIR STC	Work Card	N/A	13-Aug-2008 H: 5533.10					
	Notes / Compliance								
	N/A DUE TO PART NOT INSTALLED ON AIRCRAFT								
ASB 206L-08-151 REV.A 14,938	POWER TURBINE GOVERNOR INCREASED RELIABILITY	Work Card	N/A	27-Feb-2009 H: 5589.40					
	Notes / Compliance								
	N/A BY PART NUMBER REF. ROLLS ROYCE CEB 73-3126								
ASB 206L-08-152 14,935	MISIDENTIFICATION OF COLLECTIVE LEVER	Work Card	N/A	30-Sep-2008 H: 5567.80					
	Notes / Compliance								
	THIS ASB IS N/A BY MODEL								
ASB 206L-09-153 14,936	VERTICAL FIN ASSEMBLY INSPECTION	Work Card	N/A	30-Jan-2009 H: 5584.60					
	Notes / Compliance								
	N/A BY HELICOPTER SN								
ASB 206L-09-154 14,942	MAIN ROTOR PITCH HORN TRUNION BEARNIG CHECK	Work Card		30-Mar-2009 H: 5598.70					
	Notes / Compliance								
	INSPECTED LEVER ASSEMBLY P/N 206-001-401-111 AND FOUND BEARINGS PROPERLY STAKED								
ASB 206L-09-155 14,941	INSPECTION OF LEVER ASSEMBLY	Work Card	COMPLIED WITH	20-Mar-2009 H: 5596.40					
	Notes / Compliance								



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
ASB 206L-09-156	STACKED BEZRINGS, ONE TIME INSPECTION	Work Card		13-May-2009 H: 5599.00					
14,945			Airframe						
ASB 206L-09-158 R A	AIRWORTHINESS INSPECTION LIMITATION TO TAILBOOM LEFT UPPER ATTACHMENT FITTING (REV A)	Work Card	RECURRING		H: 100			H: 5,728.80	H: 99.50
14,956			Airframe						
ASB 206L-09-158	AIRWORTHINESS INSPECTION LIMITATION TO TAILBOOM LEFT UPPER ATTACHMENT FITTING	Work Card	SUPERSEDED	08-Sep-2009 H: 5628.80 L: 34291					
14,955			Airframe						
	Notes / Compliance	SUPERSEDED BY ASB 206L-09-158 R A							
ASB 206L-09-159 R A	MAIN ROTOR BLADE INSPECTION.	Work Card	N/A						
14,947			Airframe						
	Notes / Compliance	THIS ASB N/A BY MAIN ROTOR BLADE SN'S (A-3788 AND A-3776) P/N 206-015-001-115							
ASB 206L-09-160	VERIFICATION - FUEL FLOW CALIBRATION	Work Card	N/A						
14,951			Airframe						
	Notes / Compliance	N/A NOT REQUIRED ON 206L-4 HELICOPTERS WITH THE 250-C30P ENGINES							
ASB 206L-09-161	VERIFICATION OF FUEL FLOW CALIBRATION	Work Card	N/A						
14,950			Airframe						
	Notes / Compliance	N/A BY HELICOPTER SERIAL NUMBER							



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
ASB 206L-09-162	HYDRAULIC SERVOACTUATOR P/N 206-076-062-103, INSPECTION OF	Work Card	N/A	11-Nov-2009					
14,959			Airframe						
	Notes / Compliance	NA BY PARN NUMBER 206-076-062-101 INSTALLED ON THIS AIRCRAFT							
ASB206L-00-116 P2	C/W ASB206L-00-116 P2	Work Card		24-Jan-2001 H: 3695.00					
6,844			Airframe						
ASB206L-00-116	C/W ASB206L-00-116	Work Card		01-May-2000 H: 3308.00					
6,843			Airframe						
ASB206L-00-117	C/W ASB206L-00-117	Work Card		02-Jan-2001 H: 3636.00					
6,845			Airframe						
ASB206L-01-118	C/W ASB206L-01-118	Work Card		01-Jun-2001 H: 3884.00					
6,846			Airframe						
ASB206L-01-119	C/W ASB206L-01-119	Work Card		30-Sep-2001 H: 4031.00					
6,847			Airframe						
ASB206L-01-120	C/W ASB206L-01-120	Work Card		27-Aug-2001 H: 3981.00					
6,848			Airframe						
ASB206L-01-123	C/W ASB206L-01-123	Work Card		30-Nov-2001 H: 4042.00					
6,849			Airframe						
ASB206L-01-124	C/W ASB206L-01-124	Work Card		08-Jan-2002 H: 4042.00					
6,850			Airframe						



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
ASB206L-03-125 6,851	ASB206L-03-125 (ONE TIME)	Work Card		10-Jan-2004 H: 4801.50					
ASB206L-09-157 REV A 14,946	RECALL OF PN 101584-2 DISC ASSEMBLY	Work Card	N/A						
	Notes / Compliance	N/A PART NOT INSTALLED							
ASB206L-209-163 14,961	MAIN ROTOR BLADES P/N 206-015-001-115, /-117, /-119, /-121 SPAR SPACER, ONE TIME INSPECTION OF	Work Card	N/A	16-Dec-2009 H: 5629.30					
	Notes / Compliance	THIS ASB N/A BY BLADE S/NS (A-3788 AND A-3776) P/N 206-015-001-115.							
ASB206L-94-172 RA 6,852	ASB206L-94-172 RA	Work Card							
ASB206L-94-93 6,853	C/W ASB206L-94-93	Work Card		31-Aug-1994 H: 399.00					
ASB206L-94-95 6,854	C/W ASB206L-94-95	Work Card		12-May-1994 H: 145.00					
ASB206L-94-96 6,855	C/W ASB206L-94-96	Work Card		31-Aug-1994 H: 402.00					
ASB206L-94-97 6,856	C/W ASB206L-94-97	Work Card		23-Sep-1994 H: 449.00					



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
ASB206L-94-98 6,857	C/W ASB206L-94-98	Work Card	Airframe	23-Sep-1994 H: 449.00					
ASB206L-94-99 REV. B 6,858	C/W ASB206L-94-99 REV. B	Work Card	Airframe	08-Jan-2002 H: 4042.00					
ASB206L-94-99 6,881	C/W ASB206L-94-99	Work Card	Airframe	28-Nov-1994 H: 536.00					
ASB206L-95-101 RA 6,859	C/W ASB206L-95-101 RA	Work Card	Airframe	30-Sep-1995 H: 1023.00					
ASB206L-95-101 RB 6,860	C/W ASB206L-95-101 RB	Work Card	Airframe	03-Oct-1995 H: 1023.00					
ASB206L-95-102 6,861	C/W ASB206L-95-102	Work Card	Airframe	02-Feb-1996 H: 1175.00					
ASB206L-96-103 RA 6,863	C/W ASB206L-96-103 RA	Work Card	Airframe	06-Apr-1996 H: 1265.00					
ASB206L-96-103 6,862	C/W ASB206L-96-103	Work Card	Airframe	27-Feb-1996 H: 1203.00					
ASB206L-96-104 PART 1 6,864	C/W ASB206L-96-104 PART 1	Work Card	Airframe	02-Oct-1996 H: 1556.00					
ASB206L-96-104 REV. B 6,865	C/W ASB206L-96-104 REV. B	Work Card	Airframe	25-Oct-1998 H: 2532.00					



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
ASB206L-96-105 6,866	C/W ASB206L-96-105	Work Card	Airframe	08-Jan-1997 H: 1652.00					
ASB206L-96-106 6,867	C/W ASB206L-96-106	Work Card	Airframe	08-Jan-1997 H: 1652.00					
ASB206L-97-107 REV. A 6,869	C/W ASB206L-97-107 REV. A	Work Card	Airframe	09-Apr-1998 H: 2244.00					
ASB206L-97-107 6,868	C/W ASB206L-97-107	Work Card	Airframe	08-Oct-1997 H: 1977.00					
ASB206L-97-109 6,870	C/W ASB206L-97-109	Work Card	Airframe	12-Nov-1997 H: 2042.00					
ASB206L-98-110 6,871	C/W ASB206L-98-110	Work Card	Airframe	20-May-1998 H: 2304.00					
ASB206L-98-111 6,872	C/W ASB206L-98-111	Work Card	Airframe	26-Aug-1998 H: 2434.00					
ASB206L-98-112 REVA 6,875	C/W ASB206L-98-112 REVA	Work Card	Airframe	16-Jan-2003 H: 4488.00					
ASB206L-98-112 6,873	C/W ASB206L-98-112	Work Card	Airframe	23-Nov-2001 H: 4042.00					
ASB206L-98-112 6,874	C/W-ASB206L-98-112	Work Card	Airframe	25-Oct-1998 H: 2532.00					



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
ASB206L-98-113 PART 1 6,877	C/W ASB206L-98-113 PART 1	Work Card	Airframe	04-Jan-1999 H: 2632.00					
ASB206L-98-113 PART 2 6,876	C/W ASB206L-98-113 PART 2	Work Card	Airframe	04-Jan-1999 H: 2632.00					
ASB206L-98-114 6,878	C/W ASB206L-98-114	Work Card	Airframe	04-Jan-1999 H: 2632.00					
ASB206L-99-115 RC 6,879	C/W ASB206L-99-115 RC	Work Card	Airframe	20-Dec-1999 H: 3138.00					
ASB206L-99-115F 6,880	C/W ASB206L-99-115F	Work Card	Airframe	31-Oct-2000 H: 3139.00					
C/W ASB206-97-108 6,842	C/W ASB206-97-108	Work Card	Airframe	07-Oct-1997 H: 1977.00					
CEB 73-3126 14,937	POWER TURBINE GOVERNOR REPZIR	Work Card	Airframe	N/A 27-Feb-2009 H: 5589.40					
	Notes / Compliance	N/A BY PART NUMBER REF. HONEYWELL SB GT-73-344							
SB 206-09-195 14,962	SPANNER NUT P/N MS172242, INSPECTION OF.	Work Card	Airframe	OPEN				01-Jul-2010 H: 5,728.80	M: 5 H: 99.50



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
TB 206L-09-234 14,954	MODIFICATION OF THE 5 VOLT LIGHTING SYSTEM N/A NOT REQUIRED ON THE 206L-4 AIRCRAFT	Work Card	N/A						
	Notes / Compliance								
TB 206L-09-235 14,953	TACH GENERATOR 206-375-202-101 AND 206-076-373-001, SPLINES INSPECTION	Work Card	OPEN		M: 12 H: 600			16-Mar-2010 H: 5,929.30	M: 1 D: 15 H: 300.00
TB206L-98-114 7,010	TB206L-98-114	Work Card						17-Mar-2000	
AD 1994-15-07 AMD 39-8978 FAA 6,824	MAIN ROTOR BLADE INSPECTION	Work Card	COMPLIED WITH					30-Aug-1994 H: 399.00	
AD 1994-20-03 AMD 39-9031 FAA 6,825	MAIN ROTOR TRUNNION INSPECTON	Work Card	COMPLIED WITH					08-Dec-1994 H: 539.00	
	Notes / Compliance								
AD 1994-21-06 AMD 39-9048 FAA 6,826	LAP BELT ASSEMBLY	Work Card	COMPLIED WITH					28-Nov-1994 H: 536.00	
AD 1995-11-14 AMD 39-9247 FAA 6,827	CROSS TUBE INSPECTION / REPLACEMENT	Work Card	COMPLIED WITH					14-Jun-1995 H: 810.00	
AD 1995-24-06 AMD 39-9438 FAA 6,828	ENGINE POWER OUT WARNING SENSOR	Work Card	N/A					27-Jan-1996 H: 1153.00	
	Notes / Compliance								
	Notes / Compliance								



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
AD 1996-19-01 AMD 39-9749	SUPERIOR PARTS ENGINE FILTERS	▶ Work Card	COMPLIED WITH	02-Oct-1996 H: 1556.00					
FAA 6,819			Airframe						
AD 1997-07-07 AMD 39-9981	MAIN ROTOR AND MAST RIN HISTORY	▶ Work Card	SUPERSEDED	18-Apr-1997 H: 1760.00					
FAA 6,829			Airframe						
	Notes / Compliance	SUPERSEDED BY AD 1999-17-19							
AD 1998-14-03 AMD 39-10637	KT 76A ATC TRANSPONDER INSPECTION	▶ Work Card	COMPLIED WITH	23-Jan-2008					
FAA 6,830			Airframe						
AD 1998-24-28 AMD 39-10915	MAIN FUEL CONTROL BELLOWS REPLACEMENT	▶ Work Card	COMPLIED WITH	15-Jan-1999 H: 2671.00					
FAA 6,831			Airframe						
	Notes / Compliance	REFERENCE CEB-A-73-3068							
AD 1998-25-10 AMD 39-10936	SEAT RESTRAINT SYSTEM INSPECTION.	▶ Work Card	N/A	30-Dec-1998 H: 2633.10					
FAA 6,805			Airframe						
	Notes / Compliance	N/A DOES NOT APPLY TO THIS AIRCRAFT							
AD 1998-25-10 REV.1 AMD 39-10936	SEAT RESTRAINT SYSTEM INSPECTION	▶ Work Card	N/A	13-Jan-2000 H: 3141.00					
FAA 6,832			Airframe						
	Notes / Compliance	N/A DOES NOT APPLY TO THIS AIRCRAFT							



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
AD 1999-02-01 PART B	TAILBOOM SKIN INSPECTION / 5 HOUR TIS	Work Card	SUPERSEDED	16-Jan-1999 H: 2671.00					
FAA 6,834			Airframe						
	Notes / Compliance								
	SUPERSEDED BY AD 1999-13-12								
AD 1999-02-01 PART C	TAILBOOM SKIN INSPECTION / 25 HR TIS	Work Card	SUPERSEDED	16-Jan-1999 H: 2671.00					
FAA 6,835			Airframe						
	Notes / Compliance								
	SUPERSEDED BY AD 1999-13-12								
AD 1999-02-01 PART D	TAILBOOM SKIN INSPECTION / FLIGHT MANUAL	Work Card	SUPERSEDED	16-Jan-1999 H: 2671.00					
FAA 6,836			Airframe						
	Notes / Compliance								
	SUPERSEDED BY AD 1999-13-12								
AD 1999-02-01	TAILBOOM SKIN INSPECTION.	Work Card	SUPERSEDED	16-Jan-1999 H: 2671.00					
FAA 6,833			Airframe						
	Notes / Compliance								
	SUPERSEDED BY AD 1999-13-12								
AD 1999-13-03 AMD 39-11196	COLLECTIVE LEVER / IDLER LINK RETIREMENT	Work Card	COMPLIED WITH	22-Jul-1999 H: 2911.00					
FAA 6,820			Airframe						
	Notes / Compliance								
	REFERENCE BHT-ASB-206L-97-110								
AD 1999-13-10 AMD 39-11203	HYDRAULIC RELIEF VALVE REPLACEMENT	Work Card	COMPLIED WITH	22-Jul-1999 H: 2911.00					
FAA 6,837			Airframe						
	Notes / Compliance								
	REFERENCE BHT-ASB-206L-98-111								



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
AD 1999-1312	TAILBOOM SKIN FATIGUE CRACK INSPECTION	Work Card	SUPERSEDED	20-Dec-1999 H: 3138.00					
FAA 6,838			Airframe						
	Notes / Compliance								
	SUPERSEDED BY AD 2002-25-07								
AD 1999-17-19 AMD 39-11256	MAIN ROTOR AND MAST RIN HISTORY.	Work Card	COMPLIED WITH	12-Nov-1999 H: 3087.00					
FAA 6,839			Airframe						
	Notes / Compliance								
	SUPERSEDES AD 1997-07-07								
AD 2001-13-51 AMD 39-12443	MAIN DRIVESHAFT INSPECTION	Work Card	N/A	14-Jul-2001 H: 3948.00					
FAA 6,821			Airframe						
	Notes / Compliance								
	DRIVESHAFT NEVER INSTALLED ON BHTC MODEL 407 HELICOPTERS								
AD 2001-20-03 AMD 39-12449	HIGH ALTITUDE TAIL ROTOR STATIC STOP YIELD INDICATOR	Work Card	N/A	08-Jan-2002 H: 4042.00					
FAA 6,822			Airframe						
	Notes / Compliance								
	THIS AIRCRAFT NOT EQUIPPED WITH HIGH ALTITUDE TAIL ROTOR								
AD 2002-25-07 AMD 39-12983	HORIZONTAL STABILIZER AND TAILBOOM SKIN INSPECTION (PART F)	Work Card Task Card	RECURRING	24-Oct-2007 H: 5422.50	H: 1200			H: 6622.50	H: 993.20
FAA 6,823			Airframe						
	Notes / Compliance								
	SUPERSEDES AD 1999-13-12. COMPLIED WITH AFTER AIRCRAFT WAS PAINTED								
AD 2003-13-14 AMD 39-13216	EATON TEDECO CHIP DETECTOR INSPECTION	Work Card Task Card	COMPLIED WITH	30-Sep-2001 H: 4031.00					
FAA 14,878			Airframe						
	Notes / Compliance								
	REFERENCE BHT-ASB 206L-01-119								



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
AD 2004-24-08 AMD 39-13884	TAIL ROTOR BLADE - TAIL ROTOR WEIGHT	Work Card Task Card	SUPERSEDED	21-Mar-2005 H: 5014.20					
FAA 14,890			Airframe						
	Notes / Compliance	COMPLIED WITH ASB 206C-04-127 PART 3 ONE BLADE WAS REJECTED S/N CS8150 - SUPERSEDED BY AD 2007-01-06							
AD 2004-24-09 AMD 39-13885	REPLACEMENT OF FUEL NOZZLE	Work Card Task Card	SUPERSEDED	15-Jun-2004 H: 4850.70					
FAA 14,905			Airframe						
	Notes / Compliance	FUEL NOZZLE REPLACED UNDER CEB 73-3118 AND IS NOT SUBJECT TO THIS AD. SUPERSEDED BY AD 2006-16-04							
AD 2005-21-03 AMD 39-14341	CLEAN TAIL ROTOR BLADES AND VISUALLY CHECK BLADE ROOT DOUBLERS BEFORE FIRST FLIGHT OF EACH DAY	Work Card Task Card		26-Oct-2005 H: 5186.30					
FAA 14,897			Airframe						
	Notes / Compliance	N/A DUE TO S/N OF BLADES. CS4849 AND CS8147							
AD 2006-13-06 AMD 39-14659	TIE BOLT PART NUMBER INSPECTION & REMOVAL	Work Card Task Card	N/A	28-Jun-2006 H: 5226.90					
FAA 14,904			Airframe						
	Notes / Compliance	N/A BY ENGINE MODEL NUMBER AND TIE BOLT PART NUMBER 23008030							
AD 2006-16-04 AMD 39-14704	FUEL NOZZLE INSPECTION/REPLACEMENT	Work Card Task Card	SUPERSEDED	25-Aug-2006 H: 6244.20					
FAA 14,906			Airframe						
	Notes / Compliance	FUEL NOZZLE REPLACED UNDER CEB 73-3118. THIS FUEL NOZZLE NOT SUBJECT TO THIS AD REPLACED @ 6/15/04 ACH 4850.7. SUPERSEDED BY AD 2004-24-09							
AD 2006-20-07 AMD 39-14776	ENGINE TURBINE ASSEMBLY 3RD AND 4TH STAGE WHEEL THRESHOLD EVENT RECORDING	Work Card Task Card	COMPLIED WITH	25-Oct-2006 H: 5267.40					
FAA 14,908			Airframe						
	Notes / Compliance	INSTALLED THRESHOLD EVENT TRACKING CARDS IN ENGINE LOG BOOK, REFERENCE ROLLS ROYCE CEB-A-72-3272 ALSO PLACARDED N2 TACH.							





Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
AD 2007-01-06 AMD 39-14877	CLEAN AND INSPECT TAIL ROTOR BLADES	Work Card Task Card	COMPLIED WITH	22-Jan-2007 H: 5287.40					
FAA 14,912			Airframe						
	Notes / Compliance	SUPERSEDES AD 2004-24-08. TAIL ROTOR BLADES CURRENTLY INSTALLED ON THIS AIRCRAFT ARE P/N 206-016-201-131 S/N CS4849 AND CS8147V. THESE BLADES ARE NOT AFFECTED BY THIS AD BECAUSE OF S/N.							
AD 2007-19-52 AMD 39-15264	INSPECTION OF THE TAIL ROTOR BLADE ASSEMBLY - AMD 39-15264	Work Card Task Card	N/A	20-Dec-2007 H: 5456.60					
FAA 14,924			Airframe						
	Notes / Compliance	TAIL ROTOR BLADES ON THIS AIRCRAFT S/N CS8147V AND CS4849 ARE NOT AFFECTED BY THIS AD. ALSO REFERENCE ASB 206L-07-148 AND AD 2007-19-52 E							
AD 2007-19-52 E	INSPECTION OF THE TAIL ROTOR BLADE ASSEMBLY	Work Card	N/A	15-Sep-2007 H: 5413.90					
FAA 14,917			Airframe						
	Notes / Compliance	TAIL ROTOR BLADES ON THIS AIRCRAFT S/N CS8147V AND CS4849 ARE NOT AFFECTED BY THIS AD. ALSO REFERENCE ASB 206L-07-148							
AD 2007-22-01 AMD 39-15237	REPLACEMENT OF REPAIRED TRANSMISSION PYLON SUPPORT SPINDLE	Work Card Task Card	N/A	29-Oct-2007 H: 5422.50					
FAA 14,921			Airframe						
	Notes / Compliance	N/A BY AIRCRAFT MODEL. AD 2007-22-01 APPLIES TO 206A & 206B							
AD 2007-23-17 AMD 39-15263	REMOVAL OF CERTAIN MAIN ROTOR LATCH BOLTS	Work Card Task Card	N/A	04-Dec-2007 H: 5431.10					
FAA 14,922			Airframe						
	Notes / Compliance	N/A - THIS AD IS FOR A 206A & 206B MODEL AIRCRAFT. THE 206L-4 IS NOT SUBJECT TO THIS AD. ALSO LATCH BOLTS 206-011-260-101 INSTALLED ON THIS AIRCRAFT. THESE BOLTS NOT SUBJECT TO THIS AD.							
AD 2007-25-07 AMD 39-15289	TO DETECT IMPROPER TORQUE OF THE FIN SUPPORTS ATTACHMENT HARDWARE, GAPS BETWEEN FIN SUPPORT BRACKET AND DOUBLER	Work Card Task Card	N/A	20-Dec-2007 H: 5456.60					
FAA 14,923			Airframe						
	Notes / Compliance	N/A NOT APPLICABLE TO 206L-4 MODELS. ONLY 206A AND 206B MODELS.							



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB Item No.	Description Part No. / Serial No. / Reference No. / Other	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install /Adjustmen	Next Due	Time Remaining
AD 2008-14-03 AMD 39-15598	IMPROPER INSTALLATION OF TATTACHMENT BOLT IN UPPER LEFT TAILBOOM ATTACHMENT CRES STEEL FITTING	Work Card Task Card	PCW	15-Jul-2008 H: 5498.80					
FAA	14,932		Airframe						
	Notes / Compliance	THE INTENT OF THIS AD WAS PREVIOUSLY ACCOMPLISHED USING BHT ASB 206L-06-140 AND FOUND THAT THE UPPER LEFT TAILBOOM ATTACHMENT FITTING IS NOT CRES STEEL							
AD 2008-14-06 AMD 39-15601	MANUFACTURING FLAWS RELATED TO HORIZONTAL STABILIZER (CRACKS, DEFORMATION, AND DEBONDING AROUND AND BETWEEN INSERTS)	Work Card Task Card	N/A	15-Jul-2008 H: 5498.80					
FAA	14,933		Airframe						
	Notes / Compliance	N/A BY P/N - THIS STABILIZER WAS PREVIOUSLY INSPECTED UNDER BHT ASB206L-06-141 AND IS NOT AFFECTED BY THIS AD. HORIZONTAL STABILIZER INSTALLED IS P/N 206-023-119-151 SN 578, NO FURTHER ACTION IS REQUIRED							
AD 2009-07-51E	TO PREVENT FAILURE OF A BEARING, FAILURE OF THE CYCLIC CONTROL LEVER, AND SUBSEQUENT LOSS OF CONTROL	Work Card	COMPLIED WITH	20-Mar-2009 H: 5596.40					
FAA	14,939		Airframe						
	Notes / Compliance	INSPECTED LEVER ASSEMBLY P/N 206-001-401-111 AND FOUND BEARINGS P/N 206-301-051-101 PROPERLY INSTALLED							
AD 2009-07-52 AMD 39-15885	TO PREVENT FAILURE OF A BEARING, FAILURE OF THE LEVER ASSEMBLY, AND SUBSEQUENT LOSS OF CONTROL OF THE HELICOPTER	Work Card Task Card	COMPLIED WITH	17-Apr-2009					
FAA	14,943		Airframe						
	Notes / Compliance	THIS LEVER WAS INSPECTED 2ND FOUND BEARINGS TO BE PROPERLY STEKED. REF: 2009-07-51E AND AD 2009-07-52E							
AD 2009-08-03	REPLACE AFFECTED TAIL ROTOR BLADE WITH AIRWORTHY BLADE	Work Card	N/A						
	14,944		Airframe						
	Notes / Compliance	N/A DUE TO TAIL ROTOR BLADE S/N (CS8147V, CS 4849)							
AD 2010-03-02 AMD 39-16185	TO PREVENT FAILURE OF A HOOK DURING RESCUE HOIST OPERATION	Work Card Task Card	N/A	27-Jan-2010 H: 5629.30					
FAA	14,963		Airframe						
	Notes / Compliance	N/A THIS AIRCRAFT IS NOT EQUIPPED WITH A RESCUE HOIST							



Complete Tracked Items

N404W

Report Date: 01-Feb-2010

Reported Aircraft Times

Date: 27-Jan-2010
 Hours: 5629.30
 Landings: 34,293

Reported Engine Times

Engine 1: H: 5564.30 C: 6,529.00 CAE-895742

Aircraft / Operator Information

Weyerhaeuser
 Aircraft: BELL 206
 Serial Number: 52055
 Engine Model: 250-C30P

REV:

ATA / AD / SB	Description	Links	Disposition Group Tracked	Last Complied / Installed	Intervals *	Tolerance	Time at Install / Adjustmen	Next Due	Time Remaining
AD AD 2009-07-52E	TO PREVENT FAILURE OF A BEARING FAILURE OF THE CYCLIC CONTROL LEVER AND SUBSEQUENT LOSS OF CONTROL	Work Card	N/A						
FAA	14,940		Airframe						
	Notes / Compliance	N/A THIS LEVER P/N 206-001-401-111 HAS BEEN INSTALLED IN THIS AC IN EXCESS OF 50 HOURS REFERENCE APPLICABILITY SECTION OF AD 2009-07-52. ALOS THIS LEVER HAS BEEN PREVIOUSLY INSPECTED UNDER AD 2009-07-51E							

Total Items: 294