



# Business Aircraft Leasing, Inc.

LEASING • CONSULTING • MANAGEMENT • BROKERAGE • SALES

## 1987 HAWKER 800A

**Serial Number: NA-0401 (258100)**

**Registration: N180NE**

Total Time: 5,784

Landings: 5,369

**Engines: Garrett TFE-731-5R-1H**

**Honeywell MSP Gold Program**

	<u>L/H</u>	<u>R/H</u>
Serial Number	P-91311	P-91312
Time Since New	5,714	5,688
Cycles Since New	5,313	5,304
Time Since CZI	2,234	2,234
Time Since MPI	201	228
MPI C/W	Feb 2011	Feb 2011

**APU: Sundstrand T62-40C8D-1**

Serial Number: K00027

Total Time: 2,000 hrs

APU Starts: 2,618

### Avionics

Collins EFIS-85 EFIS System	Collins TCAS 94 TCAS II, Change 7
Collins APS 85 Autopilot/Flight Director	Collins WXR-850 Radar
Dual Collins VHF-22B Comms	Collins ALT-55B Radar Altimeter
Dual Collins VIR-32 Navs	Dual Collins RMI-30 RMIs
Dual Collins ADF-60 ADFs	Dual Universal UNS-1B FMS w/GPS
Dual Collins DME-42 DMEs	Dual King KHF-950 HF w/SELCAL
Dual Collins TDR-94D Transponders	Fairchild A-100 CVR
Dual Collins ADS-82 Air Data Computers	Flitefone VI
Dual Collins AHC-85 AHRS	Stormscope WX-1000

### Additional Features

Tell Tail Logo Lights	Thrust Reversers
Baker Audio System	Teledyne Angle of Attack
Nose Taxi Lights	Dual Davtron Clocks
Long Range O2	Right Hand Ice Light
Artex C406N (406 MHz) ELT	



404 BNA Drive • Building 200 • Suite 305  
Nashville, Tennessee 37217  
(615) 361-3781 Fax (615) 367-1226  
E-mail: [info@baliaircraft.com](mailto:info@baliaircraft.com)  
[www.baliaircraft.com](http://www.baliaircraft.com)





# Business Aircraft Leasing, Inc.

LEASING • CONSULTING • MANAGEMENT • BROKERAGE • SALES

1987 Hawker 800A, S/N: NA-0401 (258100)

Page 2 of 2

## Exterior and Interior

**Exterior:** New Nov. 2004. Overall White with Ebony and Gold Accent Stripes.

**Interior:** New Nov. 2004. The Aircraft is configured for eight passengers and features a forward Three-place divan opposite one single seat, aft four-place club seating finished with Beige Leather, Honey Maple wood work, Light Brown carpeting, a forward Galley with Microwave Oven and Coffee Maker, Two Flat Screen monitors, DVD/CD/MP3 Entertainment System, Sirius Satellite In-flight Information System and is Fireblocked.

## Maintenance Summary

<u>Inspections</u>	<u>C/W</u>	<u>Next Due</u>
B – 800 Hour	Oct. 2008 / 5,262 hrs	6,062 hrs
C – 1600 Hour	Sept. 2010 / 5,459 hrs	7,059 hrs
D – 3200 Hour	Oct. 2004 / 3,927 hrs	7,127 hrs
E – 12 Month	Sept. 2010 / 5,459 hrs	Sept. 2011
F – 24 Month	Sept. 2010 / 5,459 hrs	Oct. 2012
G – 48 Month	Sept. 2007 / 4,893 hrs	Sept. 2011
FAR 91.411	Oct. 2009 / 5,361 hrs	Oct. 2011
FAR 91.413	Oct. 2009 / 5,361 hrs	Oct. 2011

### Gear Overhaul

Hours	3,927	8,927
Date	Oct. 2004	Oct. 2016

### Thrust Reversers

200 Hour	5,361	5561
400 Hour	5,262	5661
800 Hour	5,262	6061
1600 Hour	5,262	6861

### X-Rays

Oct. 2008	Earliest X-Ray Due
	Oct. 2011

4/11

SPECIFICATION SUBJECT TO VERIFICATION UPON INSPECTION  
AIRCRAFT SUBJECT TO PRIOR SALE OR WITHDRAWAL FROM THE MARKET



404 BNA Drive • Building 200 • Suite 305  
Nashville, Tennessee 37217  
(615) 361-3781 Fax (615) 367-1226  
E-mail: [info@baliaircraft.com](mailto:info@baliaircraft.com)  
[www.baliaircraft.com](http://www.baliaircraft.com)

